Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization

Audit Name: MADISON

CLIENT INFORMATION

Client Name:

Client ID:

Alt. Client ID: 16016SW-0981

AGENCY INFORMATION

Agency: SWHRA

Address: 1574 White AVE

Henderson, TN

Address:

Agency Phone: (731) 989-5111

Fax:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-420-1409

Client Name:

Work Order (Bid Form)

DOE Weatherization Assistant

Client ID:

Alt. Client ID: 16016SW-0981

Work Order Name:

Report Run On: 5/21/2010

Version 8.5.0 Page 1 of 5

Measures

	Measure 1 Repl	lace E1 and S3 prime v	vindow		Componen	ts			Inspected
C	Comment								
				Estimated				Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Unspecified	Misc Material	Each	1				-	A-11-A-1-A-1-A-1-A-1-A-1-A-1-A-1-A-1-A-
2	Labor	Labor	Hour						
(Other Detail			ſ	1		٦		
L							J []		
				0.4	. Cut Tata!] []	Sub Total:	
,			1	weasur	e Sub Total:]	Sub Total.	
	Measure 2 Seal	Ducts			Componen				Inspected
44	Material / Labor	Denovintion / Commont	l lmita	O4.	Estimated		A 4	Actual	
	Material / Labor Construction	Description / Comment Mastic Duct boots and	<i>Units</i> Each	Qty 1	Unit Cost	Total	Qty	Unit Cost	Total
•	Materials/Hardwar		Lacii	1	A SAME	, , , , , , , , , , , , , , , , , , ,			
2	Labor	Labor	Hour						
C	Other Detail	,							
				Measur	e Sub Total:] .	Sub Total:	
	Field Notes:								

Client Name: Client ID:

Alt. Client ID: 16016SW-0981

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/21/2010

DOE Weatherization Assistant

Version 8.5.0 Page 2 of 5

	Measure 3 Gene	eral Air Sealing			Componen	ts			Inspected
C	Comment								
					Estimated	<u>. </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal pipes under master bath vanity, Seal hole in wall in master bath. Seal behind washer	Each	1					
2	Labor	Labor	Hour			VIANUAL PROPERTY.			
3	Construction Materials/Hardwar e	Seal seam where mobile home was put together, Seal pipes under kitchen sink. Seal pipes under vanity in hall	Each	1 .				Terransian de la constanta de	
4	Labor	Labor	Hour						
5	Construction Materials/Hardwar e	Seal door jam between 2 bedrooms east end	Each	1					
6	Labor	Labor	Hour					ba-polygonal	
C	Other Detail								
Γ					***************************************				
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Client Name: Client ID: Work Order (Bid Form)

DOE Weatherization Assistant

Alt. Client ID: 16016SW-0981

Work Order Name:

Report Run On: 5/21/2010

	/H Pipe Insulation	4.		Componen	ts		4 4944	Inspected
Comment				Estimated			Actual	LJ
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DWH Pipe Insulation	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			-					
			Measur	e Sub Total:			Sub Total:	
Measure 5 Bel	ly Fiberglass Loose			Componen	ts			Inspected
				Estimated				
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Replace floor insulation where needed	Each	35					
2 Labor	Floor Insulation - Fbergls,Blwn	Hour					franco	THE ACTION AND ADDRESS AND ADD
Other Detail			general natural natural states and a simple st	Kanadaring transmission for the second	P- WWW. ADVINS - AND - A	, ,		TO TOOL OTTO THE
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Report Run On: 5/21/2010

Measure 6 DWF	l Tank Insulation			Componen	ts		1	nspected
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DWH Tank Insulation	Each	1					
2 Labor	Labor	Each	1					
Other Detail				1		7 [
			Measur	e Sub Total:			Sub Total:	
Measure 7 Pres	sureRelief Piping Nee	ded		Componen	ts		I.	nspected
				Estimated	**************************************	**********************	Actual	· · · · · · · · · · · · · · · · · · ·
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	Pressure relief piping	Each	1					
2 Labor	Labor	Hour	1					
Other Detail				I		-	,	***************************************
] []		
] []	Sub Total:	
Field Notes:			vieasur	e Sub Total:			oun Total:	
		Work Ore	der Gra	nd Total:		Grand	d Total:	